







This older development was flagged by a CASp report with numerous barriers to be remediated: the store front sidewalk cross slope was non compliant, several unsuccessful efforts had been made to correct the ADA parking layout, and there was no accessible route to the public sidewalk.











savings to the owners.

serving as the path of travel to the city sidewalk, avoiding costly ramping and railings.

